

[howto](#), [debianbrother](#), [printer](#), [cups](#), [driver](#), [mfcl3750cdw](#), [xsane](#), [sane](#), [scanner](#)

## Debian - Brother MFC-L3750CDW

- [https://support.brother.com/g/b/downloadlist.aspx?c=de&lang=de&prod=mfcl3750cdw\\_us\\_eu\\_as&os=128&flang=English](https://support.brother.com/g/b/downloadlist.aspx?c=de&lang=de&prod=mfcl3750cdw_us_eu_as&os=128&flang=English)

To install LPR, CUPSwrapper driver and scanner driver (for scanner models), download the "Driver Install Tool" (linux-brprinter-installer-\*.\*.\*.gz).

```
MYUSER="YOURUSERNAME"; MYGROUP="{MYUSER}"
mkdir -pv /home/$MYUSER/repos/extern/brother/
mv /home/$MYUSER/Downloads/linux-brprinter-installer-*.*.*.gz /home/$MYUSER/repos/extern/brother/
gunzip -v -k -c /home/$MYUSER/repos/extern/brother/linux-brprinter-installer-*.*.*.gz >
/home/$MYUSER/repos/extern/brother/linux-brprinter-installer.sh
chown -R $MYUSER:$MYGROUP /home/$MYUSER/repos/extern/brother/
chmod u+x /home/$MYUSER/repos/extern/brother/linux-brprinter-installer.sh
/home/$MYUSER/repos/extern/brother/linux-brprinter-installer.sh MFC-L3750CDW
```

The driver installation will start. Follow the installation screen directions.

When you see the message "Will you specify the DeviceURI ?",

- For USB Users: Choose N(No)
- For Network Users: Choose Y(Yes) and DeviceURI number.

The install process may take some time. Please wait until it is complete.

```
apt install xsane
```

From:  
<https://wiki.nanoscopic.de/> - nanoscopic wiki

Permanent link:  
[https://wiki.nanoscopic.de/doku.php/pages/howtos/debian/brother\\_mfc-l3750cdw?rev=1614548492](https://wiki.nanoscopic.de/doku.php/pages/howtos/debian/brother_mfc-l3750cdw?rev=1614548492)

Last update: **2021/02/28 21:41**

